




Boraam Industries

ASSEMBLY INSTRUCTIONS

SKU: 36724 | COLORADO 24" STEP STOOL



Weight Capacity



Locate the **HARDWARE PACK** which is attached to the shipping carton with red tape.

12/2024



Have questions about assembling your item?



Items or parts damaged?



Missing a part?

We're here to help! (Monday-Friday from 9am-5pm CST)



847-949-6300
877-267-2261



customerservice@
boraamindustries.com



www.boraamindustries.com







Philips screwdriver
not included.

Assembly And Care


- All tools required for assembly are included unless noted.
- Prior to assembly, check for missing or damaged parts.
- Do not dispose of packing materials until assembly is completed.
- Assemble item on a soft, clean surface to prevent damage to the item.













Locate the
HARDWARE PACK
which is attached to the
shipping carton with red
tape.









Assembly Overview




PARTS

<div>① (x1)</div> <div>Top panel:</div> <div><p>Felt tape</p></div>	<div>② (x1)</div> <div>Left:</div> <div><p>Metal latch</p></div>	<div>③ (x1)</div> <div>Right:</div> <div></div>	<div>④ (x2)</div> <div>Bottom step:</div> <div><div>④a</div><div>④b</div></div>	
<div>⑤ (x1)</div> <div>Left:</div> <div></div>	<div>⑥ (x1)</div> <div>Right:</div> <div></div>	<div>⑦ (x2)</div> <div></div>	<div>⑧ (x2)</div> <div></div>	<div>⑨ (x1)</div> <div></div>

HARDWARE

Ⓐ (x8)	Ⓑ (x12)	Ⓒ (x8)	Ⓓ (x2)	Ⓔ (x12)	Ⓕ (x1)
					
Bolt M6x35	Screw M6x30	Flat Washer	Screw M4x35	Wood Button	Allen Wrench



01



Hardware	Count
A	8
C	8
F	1

DO NOT TIGHTEN BOLT COMPLETELY.

02




4X

Hardware	Count
B	4
F	1

DO NOT TIGHTEN SCREW COMPLETELY.


03



Hardware	Count
D	2

TIGHTEN SCREW COMPLETELY.


04





Hardware	Count
B	4
F	1

TIGHTEN SCREW COMPLETELY.

05



06




4X

Hardware	Count
B	4
F	1

TIGHTEN BOLT AND SCREW COMPLETELY.


07



Hardware	Count
E	12



Weight Capacity



BE SURE TO CHECK ALL BOLTS ARE SECURELY TIGHTENED PRIOR TO USE.