




Boraam Industries

ASSEMBLY INSTRUCTIONS

SKU: 12508 | SONOMA KITCHEN CART WITH DROP LEAF



Weight Capacity



Locate the
HARDWARE PACK
which is attached to the
shipping carton with red tape.

18/08/2024



Have questions about
assembling your item?



Items or parts damaged?



Missing a part?

We're here to help! (Monday-Friday from 9am-5pm CST)



847-949-6300
877-267-2261



customerservice@
boraamindustries.com



www.boraamindustries.com

Phillips
Screwdriver
(Not provided)







Assembly And Care


- All tools required for assembly are included unless noted.
- Prior to assembly, check for missing or damaged parts.
- Do not dispose of packing materials until assembly is completed.
- Assemble item on a soft, clean surface to prevent damage to the item.









Locate the
HARDWARE PACK
which is attached to the
shipping carton with red
tape.












Assembly Overview




PARTS

① (x1)	② (x1)
Top with Drawers: 	Middle shelf: 
③ (x1)	④ (x1)
Bottom shelf: 	Left leg: 
⑤ (x1)	⑥ (x1)
Right leg: 	Rack: 

HARDWARE

Ⓐ (x16)	Ⓑ (x8)	Ⓒ (x2)	Ⓓ (x2)	Ⓔ (x4)	Ⓕ (x8)	Ⓖ (x8)	Ⓗ (x1)	Ⓘ (x1)
								
Wood Nut	Flat Washer M6x16	Caster	Caster with lock	Bolt M6x35	Bolt M6x50	Bolt M6x60	Allen Wrench	Wrench K13


01



Hardware	Count
E	4
H	1

TIGHTEN BOLT COMPLETELY.

02





8X

Hardware	Count
B	8
F	8
H	1

DO NOT TIGHTEN BOLT COMPLETELY.


03

1. Make sure the insert nuts are in the correct position before assembling.
2. You will need a screwdriver to turn the nuts into the correct position as shown below.



This is to prepare for step 04


04



Hardware	Count
G	4
H	1

DO NOT TIGHTEN BOLT COMPLETELY.


05



Hardware	Count
G	4
H	1

TIGHTEN BOLT COMPLETELY.


06



Hardware	Count
D	2
C	2
I	1

TIGHTEN BOLT COMPLETELY.

07



Hardware	Count
A	16



Weight Capacity

BE SURE TO CHECK ALL BOLTS ARE SECURELY TIGHTENED PRIOR TO USE.