




# Boraam Industries

ASSEMBLY INSTRUCTIONS

SKU: 52129,52229,52329,52429 | JONES SWIVEL STOOL



Weight Capacity



Locate the  
**HARDWARE PACK**  
which is attached to  
the shipping carton  
with red tape.

02/2024



Have questions about  
assembling your item?



Items or parts damaged?



Missing a part?

**We're here to help! (Monday-Friday from 9am-5pm CST)**



847-949-6300  
877-267-2261



customerservice@  
boraamindustries.com






www.boraamindustries.com

# Assembly And Care


- All tools required for assembly are included unless noted.
- Prior to assembly, check for missing or damaged parts.
- Do not dispose of packing materials until assembly is completed.
- Assemble item on a soft, clean surface to prevent damage to the item.










Locate the  
**HARDWARE PACK**  
which is attached to the  
shipping carton with red  
tape.



# Assembly Overview













# PARTS

<p>①(x1)</p> <p><b>Backrest :</b></p> 	<p>②(x4)</p> <p><b>Legs :</b></p> 
<p>③(x1)</p> <p><b>Footrest :</b></p> 	<p>⑤(x1)</p> <p><b>Seat Cushion :</b></p> 
<p>④(x1)</p> <p><b>Apron With Swivel Plate :</b></p> 	<p>⑦(x1)</p> <p><b>Right Armchair:</b></p> 
<p>⑥(x1)</p> <p><b>Left Armchair:</b></p> 	


847-949-6300 | 877-267-2261 | [customerservice@boraamindustries.com](mailto:customerservice@boraamindustries.com)

# HARDWARE

(A)(x22)	(B)(x2)	(C)(x26)	(D)(x2)	(E)(x4)
				
Spring Washer M6*10	Flat Washer M6*13	Flat Washer M6*16	Wood Button Ø7.5x15.5	Bolt M6*35
(F)(x12)	(G)(x6)	(H)(x2)	(I)(x4)	(J)(x1)
				
Bolt M6*40	Bolt M6*45	Bolt M6*50	Bolt M6*60	Allen Wrench M4*110


847-949-6300 | 877-267-2261 | [customerservice@boraamindustries.com](mailto:customerservice@boraamindustries.com)

# 01



DO NOT TIGHTEN BOLT COMPLETELY



# 02



TIGHTEN BOLT COMPLETELY.



# 03




Hardware	Count
C	4
E	4
J	1



TIGHTEN BOLT COMPLETELY.



# 04




2X




2X

Hardware	Count
A	4
B	2
C	4
D	2
G	4
H	2
J	1

TIGHTEN BOLT COMPLETELY.



**Weight Capacity**



**BE SURE TO CHECK ALL BOLTS ARE SECURELY TIGHTENED PRIOR TO USE.**