




Boraam Industries

ASSEMBLY INSTRUCTIONS

SKU: 77320,77322,77323,77325,77326

RASMUS CONSOLE TABLE



Prior to assembly, please consult the instruction video on our website.

Version 4 / Updated as of 05.24

<https://boraamindustries.com/boraam/rasmus-console-table/>



Have questions about assembling your item?



Items or parts damaged?



Missing a part?

We're here to help! (Monday-Friday from 9am-5pm CST)



847-949-6300
877-267-2261



customerservice@
boraamindustries.com







www.boraamindustries.com

Assembly And Care


- All tools required for assembly are included unless noted.
- Prior to assembly, check for missing or damaged parts.
- Do not dispose of packing materials until assembly is completed.
- Assemble item on a soft, clean surface to prevent damage to the item.



Locate the **HARDWARE PACK** which is attached to the shipping carton with red tape.




A




Threaded rod
M8*40
1 PC

B




Plastic Washer
1 PC

C




M8*40
8 PCS

D




1 PC





01

2




B

A



TIGHTEN BOLT COMPLETELY.



02



Turn two legs to tighten


TIGHTEN BOLT COMPLETELY.

03



TIGHTEN BOLT COMPLETELY.

04





Remove wooden board connector from table top with Allen key provided. Please keep the hardware for step 06.






Refer to the instructional video on our website before attempting this step.

<https://boraamindustries.com/boraam/rasmus-console-table/>

! Hardware Included



05





Align wooden board connector to match A - A, B - B


TIGHTEN BOLT COMPLETELY.

06

Hardware Included



-Align all bolts with the bolt holes and turn by finger 2 turns.
-Once All bolts alignment is confirmed, tighten securely using provided allen key.



Warning:

Serious injuries can occur from the Console table tip-over

BE SURE TO CHECK ALL BOLTS ARE SECURELY
TIGHTENED PRIOR USING THIS TABLE.