




Boraam Industries

ASSEMBLY INSTRUCTIONS

SKU: **08824**, 48824, 48829, 45824, 45829
46824, 46829, 49824, 49829, 52824, 52829, 58824
AUGUSTA SWIVEL STOOL



Weight Capacity



Locate the
HARDWARE PACK
which is attached to
the shipping carton
with red tape.

11/25



Have questions about
assembling your item?



Items or parts damaged?



Missing a part?

We're here to help! (Monday-Friday from 9am-5pm CST)



847-949-6300
877-267-2261



customerservice@
boraamindustries.com







www.boraamindustries.com

Assembly And Care


- Two people are recommended for ease of assembly.
- All tools required for assembly are included unless noted.
- Prior to assembly, check for missing or damaged parts.
- Do not dispose of packing materials until assembly is completed.
- Assemble item on a soft, clean surface to prevent damage to the item.








Locate the
HARDWARE PACK
which is attached to the
shipping carton with red
tape.









Assembly Overview



PARTS


①(x1)	②(x4)	③(x1)
Backrest : 	Legs : 	Footrest : 
④(x1)	⑤(x1)	
Apron With Swivel Plate : 	Seat Cushion : 	

HARDWARE



Ⓐ(x22)	Ⓑ(x26)	Ⓒ(x4)	Ⓓ(x16)	Ⓔ(x6)	Ⓕ(x1)
					
Spring Washer M6*10	Flat Washer M6*16	Bolt M6*25	Bolt M6*40	Bolt M6*50	Allen Wrench M4*110

847-949-6300 | 877-267-2261 | customerservice@boraamindustries.com

01




4X



Hardware	Count
A	8
B	8
D	8
F	1

DO NOT TIGHTEN BOLT COMPLETELY.


02




Hardware	Count
A	8
B	8
D	8
F	1

TIGHTEN BOLT COMPLETELY.

03



3X





Hardware	Count
A	6
B	6
E	6
F	1

TIGHTEN BOLT COMPLETELY.


847-949-6300 | 877-267-2261 | customerservice@boraamindustries.com

04





Hardware	Count
B	4
C	4
F	1

TIGHTEN BOLT COMPLETELY.



Weight Capacity



BE SURE TO CHECK ALL BOLTS ARE SECURELY TIGHTENED PRIOR TO USE.