




Boraam Industries

ASSEMBLY INSTRUCTIONS

**SKU: 94924,94929,94824,94829,94324
94329,94124,94129,94424,95424,94024
SQUARE RUSH STOOL**



Weight Capacity



Locate the
HARDWARE PACK
which is attached to
the shipping carton
with red tape.

10/2024



Have questions about
assembling your item?



Items or parts damaged?



Missing a part?

We're here to help! (Monday-Friday from 9am-5pm CST)



847-949-6300
877-267-2261



customerservice@
boraamindustries.com



www.boraamindustries.com







Philips screwdriver
not included.

Assembly And Care


- All tools required for assembly are included unless noted.
- Prior to assembly, check for missing or damaged parts.
- Do not dispose of packing materials until assembly is completed.
- Assemble item on a soft, clean surface to prevent damage to the item.







Locate the
HARDWARE PACK
which is attached to the
shipping carton with red
tape.






Assembly Overview



PARTS


①(x2)	②(x1)
<p>Leg :</p> 	<p>Seat:</p> 
③(x2)	④(x4)
<p>Apron :</p> 	<p>Stretcher :</p> 

HARDWARE

Ⓐ(x8)	Ⓑ(x12)	Ⓒ(x1)
		
<p>Bolt M6*40</p>	<p>Wood Screw M4*35</p>	<p>Allen Wrench M4*110</p>

847-949-6300 | 877-267-2261 | customerservice@boraamindustries.com


01



Attach part 3 by following the arrow direction shown in the picture above to ensure correct alignment.


DO NOT TIGHTEN BOLT AND SCREW COMPLETELY.

02



Hardware	Count
B	4

TIGHTEN BOLT AND SCREW COMPLETELY.



Weight Capacity

BE SURE TO CHECK ALL BOLTS ARE SECURELY TIGHTENED PRIOR TO USE.

847-949-6300 | 877-267-2261 | customerservice@boraamindustries.com