




# Boraam Industries

ASSEMBLY INSTRUCTIONS

SKU:40224,40229,40324,40329 | CATHEDRAL SWIVEL STOOL



Weight Capacity



Locate the  
**HARDWARE PACK**  
which is attached to  
the shipping carton  
with red tape.

02/2024



Have questions about  
assembling your item?



Items or parts damaged?



Missing a part?

**We're here to help! (Monday-Friday from 9am-5pm CST)**



847-949-6300  
877-267-2261



customerservice@  
boraamindustries.com






www.boraamindustries.com

# Assembly And Care


- All tools required for assembly are included unless noted.
- Prior to assembly, check for missing or damaged parts.
- Do not dispose of packing materials until assembly is completed.
- Assemble item on a soft, clean surface to prevent damage to the item.








Locate the  
**HARDWARE PACK**  
which is attached to the  
shipping carton with red  
tape.











# Assembly Overview




# PARTS

<div>①(x1)</div> <div>Backrest :</div> <div></div>	<div>②(x4)</div> <div>Legs :</div> <div></div>	
<div>③(x1)</div> <div>Footrest :</div> <div></div>	<div>④(x1)</div> <div>Apron With Swivel Plate :</div> <div></div>	<div>⑤(x1)</div> <div>Seat Cushion :</div> <div></div>



# HARDWARE

①A(x14)	①B(x4)	①C(x18)	①D(x4)	①E(x8)	①F(x6)	①G(x4)	①H(x1)
							
Spring Washer M6*10	Flat Washer M6*13	Flat Washer M6*16	Bolt M6*25	Bolt M6*40	Bolt M6*50	Bolt M6*70	Allen Wrench M4*110

# 01






4X



Hardware	Count
A	8
C	8
E	8
H	1

DO NOT TIGHTEN BOLT COMPLETELY.



# 02



Hardware	Count
B	4
G	4
H	1

TIGHTEN BOLT COMPLETELY.



# 03



Hardware	Count
A	6
C	6
F	6
H	1

TIGHTEN BOLT COMPLETELY.

# 04




4X


Hardware	Count
C	4
D	4
H	1

TIGHTEN BOLT COMPLETELY.





**Weight Capacity**



**BE SURE TO CHECK ALL BOLTS ARE SECURELY TIGHTENED PRIOR TO USE.**