




Boraam Industries

ASSEMBLY INSTRUCTIONS

SKU: 70736 | COLORADO TABLE



Weight Capacity



Locate the
HARDWARE PACK
which is attached to
the shipping carton
with red tape.

01/2024



Have questions about
assembling your item?



Items or parts damaged?



Missing a part?

We're here to help! (Monday-Friday from 9am-5pm CST)



847-949-6300
877-267-2261



customerservice@
boraamindustries.com



www.boraamindustries.com







Philips screwdriver
not included.

Assembly And Care


- All tools required for assembly are included unless noted.
- Prior to assembly, check for missing or damaged parts.
- Do not dispose of packing materials until assembly is completed.
- Assemble item on a soft, clean surface to prevent damage to the item.





Locate the
HARDWARE PACK
which is attached to the
shipping carton with red
tape.







Assembly Overview




PARTS

<div>① (x1)</div>
<div>Top Panel :</div> <div>  </div>
<div>② (x4)</div>
<div>Leg :</div> <div>  </div>


HARDWARE

<div>Ⓐ (x8)</div>	<div>Ⓑ (x8)</div>	<div>Ⓒ (x8)</div>	<div>Ⓓ (x1)</div>
<div>  </div>	<div>  </div>	<div>  </div>	<div>  </div>
<div>Spring Washer</div>	<div>Flat Washer</div>	<div>Bolt M8x70</div>	<div>Allen Wrench</div>

01



02




Hardware	Count
A	8
B	8
C	8
D	1

TIGHTEN BOLT COMPLETELY.



Weight Capacity



BE SURE TO CHECK ALL BOLTS ARE SECURELY TIGHTENED PRIOR TO USE.