




Boraam Industries

ASSEMBLY INSTRUCTIONS

SKU: 41224, 41229, 45225, 45230 | KYOTO SWIVEL STOOL



Weight Capacity



Locate the
HARDWARE PACK
which is attached to
the shipping carton
with red tape.

02/2024



Have questions about
assembling your item?



Items or parts damaged?



Missing a part?

We're here to help! (Monday-Friday from 9am-5pm CST)



847-949-6300
877-267-2261



customerservice@
boraamindustries.com






www.boraamindustries.com

Assembly And Care


- All tools required for assembly are included unless noted.
- Prior to assembly, check for missing or damaged parts.
- Do not dispose of packing materials until assembly is completed.
- Assemble item on a soft, clean surface to prevent damage to the item.







Locate the
HARDWARE PACK
which is attached to the
shipping carton with red
tape.








Assembly Overview



PARTS


①(x1) Backrest : 	②(x4) Legs : 	③(x1) Footrest : 
④(x1) Apron With Swivel Plate : 	⑤(x1) Seat Cushion : 	

HARDWARE


Ⓐ(x22)  Spring Washer M6*13	Ⓑ(x26)  Flat Washer M6*16	Ⓒ(x4)  Bolt M6*25	Ⓓ(x16)  Bolt M6*40	Ⓔ(x6)  Bolt M6*50	Ⓕ(x1)  Allen Wrench M4*110
--	--	--	---	--	---

847-949-6300 | 877-267-2261 | customerservice@boraamindustries.com

01




4X



Hardware	Count
A	8
B	8
D	8
F	1



DO NOT TIGHTEN BOLT COMPLETELY.

02



DO NOT TIGHTEN BOLT COMPLETELY.


03



Hardware	Count
A	6
B	6
E	6
F	1


TIGHTEN BOLT COMPLETELY.

04




Hardware	Count
B	4
C	4
F	1

TIGHTEN BOLT COMPLETELY.



Weight Capacity



BE SURE TO CHECK ALL BOLTS ARE SECURELY TIGHTENED PRIOR TO USE.