




Boraam Industries

ASSEMBLY INSTRUCTIONS

SKU: 71369 | CAROLINA TABLE



Weight Capacity



Locate the
HARDWARE PACK
which is attached to
the shipping carton
with red tape.

01/2024



Have questions about
assembling your item?



Items or parts damaged?



Missing a part?

We're here to help! (Monday-Friday from 9am-5pm CST)



847-949-6300
877-267-2261



customerservice@
boraamindustries.com



www.boraamindustries.com







Philips screwdriver
not included.

Assembly And Care


- All tools required for assembly are included unless noted.
- Prior to assembly, check for missing or damaged parts.
- Do not dispose of packing materials until assembly is completed.
- Assemble item on a soft, clean surface to prevent damage to the item.




Locate the
HARDWARE PACK
which is attached to the
shipping carton with red
tape.







Assembly Overview




PARTS

① (x1)	
Top Panel:	
② (x4)	
Leg:	


HARDWARE

Ⓐ (x8)	Ⓑ (x8)	Ⓒ (x8)	Ⓓ (x1)
			
Spring Washer	Flat Washer	Bolt M8x70	Allen Wrench

01



02




Hardware	Count
A	8
B	8
C	8
D	1

TIGHTEN BOLT COMPLETELY.



Weight Capacity




BE SURE TO CHECK ALL BOLTS ARE SECURELY TIGHTENED PRIOR TO USE.



Boraam Industries

ASSEMBLY INSTRUCTIONS

SKU: 31616 | CAROLINA DINING CHAIR



Weight Capacity



Locate the
HARDWARE PACK
which is attached to
the shipping carton
with red tape.

12/2024



Have questions about
assembling your item?



Items or parts damaged?



Missing a part?

We're here to help! (Monday-Friday from 9am-5pm CST)



847-949-6300
877-267-2261



customerservice@
boraamindustries.com



www.boraamindustries.com







Philips screwdriver
not included.

Assembly And Care


- All tools required for assembly are included unless noted.
- Prior to assembly, check for missing or damaged parts.
- Do not dispose of packing materials until assembly is completed.
- Assemble item on a soft, clean surface to prevent damage to the item.










Locate the
HARDWARE PACK
which is attached to the
shipping carton with red
tape.





Assembly Overview





PARTS


① (x1) Hoop: 	② (x1) Seat: 
③ (x1) Leg Frame-Left: 	④ (x1) Leg Frame-Right: 
⑤ (x2) Long Spindle: 	⑥ (x2) Medium Spindle: 
⑦ (x2) Short Spindle: 	⑧ (x1) Crossbar: 

HARDWARE


Ⓐ (x4)	Ⓑ (x8)	Ⓒ (x8)	Ⓓ (x4)	Ⓔ (x1)
				
Bolt M6x60	Spring Washer	Flat Washer	Barrel Nut M6x13	Allen Wrench

Ⓕ (x2)	Ⓖ (x2)	Ⓗ (x6)	Ⓘ (x6)	Ⓝ (x1)
				
Wood Button	Wood Button	Screw M4x30	Bolt M6x35	Glue Tube


01



Do not use Power Tools
to assemble.




6X




Hardware	Count
H	6

02




03



Hardware	Count
A	2
B	2
C	2
D	2
E	1


04



Hardware	Count
A	2
D	2
E	1

DO NOT TIGHTEN BOLT COMPLETELY.

05




Hardware	Count
I	6
B	6
C	6
E	1




Scan the QR code for a video explaining this step.

TIGHTEN BOLT COMPLETELY.

06



Hardware	Count
F	2
G	2



Weight Capacity

BE SURE TO CHECK ALL BOLTS ARE SECURELY TIGHTENED PRIOR TO USE.

847-949-6300 | 877-267-2261 | customerservice@boraamindustries.com