


## **Boraam Industries**

**ASSEMBLY INSTRUCTIONS** 

#### SKU: 77334 | RASMUS EXTENSION DINING TABLE



02/2024



Have questions about assembling your item?



Items or parts damaged?



Missing a part?

#### We're here to help! (Monday-Friday from 9am-5pm CST)



847-949-6300 877-267-2261



customerservice@ boraamindustries.com




www.boraamindustries.com

Page 1 of 12


# **Assembly And Care**

- All tools required for assembly are included unless noted.
- Prior to assembly, check for missing or damaged parts.
- Do not dispose of packing materials until assembly is completed.
- Assemble item on a soft, clean surface to prevent damage to the item.








#### **PARTS**





## **HARDWARE**















# 05










BE SURE TO CHECK ALL BOLTS ARE SECURELY TIGHTENED PRIOR TO USE.



## **Boraam Industries**

**ASSEMBLY INSTRUCTIONS** 

#### SKU: 77316,77319 I RASMUS DINING CHAIR





**Weight Capacity** 



Locate the **HARDWARE PACK** which is attached to the shipping carton with red tape.

01/2024



Have questions about assembling your item?



Items or parts damaged?



Missing a part?

#### We're here to help! (Monday-Friday from 9am-5pm CST)



847-949-6300 877-267-2261



customerservice@ boraaamindustries.com



www.boraamindustries.com


Page 1 of 10

## **Assembly And Care**


- All tools required for assembly are included unless noted.
- Prior to assembly, check for missing or damaged parts.
- Do not dispose of packing materials until assembly is completed.
- Assemble item on a soft, clean surface to prevent damage to the item.




# **Assembly Overview**




### **PARTS**



#### **HARDWARE**




01




Hardware	Count
D	4

TIGHTEN THREADED ROD COMPLETELY.




Hardware	Count
Α	4
В	4
E	4
I	1

TIGHTEN HEX NUT COMPLETELY.




Hardware	Count
F	4




Hardware	Count
Α	4
В	4
G	4
Н	1

DO NOT TIGHTEN BOLT COMPLETELY.



Hardware	Count
С	2
Н	1

TIGHTEN BOLT COMPLETELY.



BE SURE TO CHECK ALL BOLTS ARE SECURELY TIGHTENED PRIOR TO USE.